


# S-100 Assembly Procedure



System ITX Mother Board

The Front View



( Photo for your reference only)

The Rear View



## Accessories

Name	Type	Item	Quantity	Application
SATA Cable	#1.		1	Fot SATA HDD
Screw	M3	#1.	4	For HDD
	6# -32 hexagon	#2.	4	For MB

## Specifications:

Model Name	S100 case
Dimension	190 x 200 x 70 mm (D x W x H)
Weight	1 kg (with cable)
Form Factor	mini iTX
Front IO (optional)	USB2.0 x 2, Audio x 1, MIC x 1
Material	2.0mm Aluminum


**AOpen Inc.**

Tel: 886-2-77101195  
Fax: 886-2-77101187

Web site: <http://global.aopen.com>  
Address: No. 68, Rueiguang Road,  
Taipei, Taiwan, 11491, R.O.C.



The back of the chassis.




Unscrew 4 screws on the back of chassis.




Take the back panel out of the chassis.



Take the HDD cage out of the chassis.



The HDD cage.



For HDD cage need to fix 2 screws on chassis.



Take the rubber out of the chassis bottom.



Install mounting kit into the cage bottom.



Fix 1 screw on the back of monitor.